| TENDE | R COMPARISON FORM | | | | | | | Page 1 of 2 | | |
|---------|---|------------------|----------|---------------------------------------|----------------------|--------------|-----|--------------|--|--|
| | | | | | | | | | | |
| SP3840 |) | | | | | | | | | |
| 51-53 T | HE CRESCENT | | | | | | | | | |
| MANLY | (| | | | | | | | | |
| | | | | | | | | | | |
| Mar-21 | | | | | | | | | | |
| | | | | All costs include GST | | | | | | |
| ITEM | DESCRIPTION | | RBS FBS | | | СВС | | | | |
| | Fixed Costs Façade | | | | | | | | | |
| 1 | Site establishment & access | | \$ | 370,000.00 | \$ | 466,701.00 | \$ | 798,396.00 | | |
| 2 | Nominated balcony works as per Sutech | | | | | | | | | |
| | schedule | | \$ | 682,600.00 | \$ | 662,333.00 | \$ | 662,071.00 | | |
| 3 | Nominated cavity flashings | | \$ | 148,720.00 | \$ | 93,808.00 | \$ | 80,180.00 | | |
| 5 | Expansion joints | | \$ | 14,300.00 | \$ | 26,315.00 | \$ | 22,308.00 | | |
| 6.1 | Stripping of existing coatings (200sqm) | | \$ | 36,000.00 | \$ | 41,855.00 | \$ | 51,731.68 | | |
| 6.2 | Concrete Spalling (1500 litres) | | \$ | 99,000.00 | \$ | 79,200.00 | \$ | 75,000.00 | | |
| 7 | Coatings | | \$ | 159,000.00 | \$ | 140,672.00 | \$ | 158,245.00 | | |
| 8 | General external coatings | | \$ | 84,500.00 | \$ | 73,837.00 | \$ | 112,215.00 | | |
| 9 | Clean up | | \$ | 6,500.00 | \$ | 1,980.00 | \$ | 7,150.00 | | |
| 11 | Roof membrane replacement | | \$ | 173,900.00 | \$ | 125,338.00 | \$ | 192,399.00 | | |
| | Total fixed costs | | \$ | 1,774,520.00 | \$ | 1,712,039.00 | \$ | 2,159,695.68 | | |
| | | | | · · · · · · · · · · · · · · · · · · · | | | | | | |
| | | | | | | | | | | |
| | | | | | All costs include GS | | | | | |
| ITEM | DESCRIPTION | | | RBS | | FBS | | СВС | | |
| Balcon | y works - Rates | | | | | | | | | |
| 2 | Small balcony membrane replacement | per balcony | \$ | 23,500.00 | \$ | 19,013.00 | \$ | 6,081.00 | | |
| 2 | Large Balcony membrane replacement | per balcony | \$ | 35,500.00 | \$ | 32,011.00 | \$ | 12,368.00 | | |
| 2 | Balcony sliding door supply cost | per door | \$ | 5,000.00 | \$ | 6,699.00 | \$ | 8,221.00 | | |
| 2 | Balcony hinged door replacement cost | per door | \$ | 4,000.00 | \$ | 2,090.00 | \$ | 4,235.00 | | |
| 10 | A1. Concrete hob replacement (per door) | per sliding door | <u> </u> | .,000.00 | <u> </u> | | Ť | .,_00.00 | | |
| | | hob | \$ | 2,100.00 | \$ | 1,683.00 | \$ | 2,536.00 | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | All costs in | osts include GST | | | | | |
| ITEM | DESCRIPTION | | RBS | | FBS | | СВС | | | |
| Façade | | | | | | | | | | |
| 6.1 | 1. Remove coatings from balcony parapet walls | both sides of a | | | | | | | | |
| | | single balcony | | | | | | | | |
| | | parapet | \$ | 750.00 | \$ | 713.00 | \$ | 1,035.00 | | |
| | 2. Remove coatings from balcony soffits(small) | per soffit | \$ | 1,800.00 | \$ | 2,382.00 | \$ | 3,165.00 | | |
| | 3. Remove coatings from balcony soffits (large) | per soffit | \$ | 2,500.00 | \$ | 3,267.00 | \$ | 6,859.00 | | |
| | 3. Remove coatings from columns | per column | \$ | 1,450.00 | \$ | 1,287.00 | \$ | 2,849.00 | | |
| | 4. All other surfaces | sq/m | \$ | 180.00 | \$ | 198.00 | \$ | 263.00 | | |
| 6.2 | Concrete spalling | per litre | \$ | 66.00 | \$ | 55.00 | \$ | 50.00 | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | Rates for Cost Plus Works if required | | | RBS | | FBS | | CBC | | |
| | Labour \$ per man hour including GST | | \$ | 99.00 | \$ | 90.00 | \$ | 90.00 | | |
| | Contractor margin % | | | 20% | | 18% | | 20% | | |
| | | | | | | <u> </u> | | <u> </u> | | |
| | Contract duration weeks | | | 22 | | 36 | | 30-32 | | |
| | | | | | | | | | | |
| _ | | | _ | | _ | | | | | |

| TENDER COMPARISON FORM | | | | | | Page 2 of 2 | | | |
|--|----|-----------------------|----|--------------|-----|--------------|--|--|--|
| | | | | | | | | | |
| SP3840 | | | | | | | | | |
| 51-53 THE CRESCENT | | | | | | | | | |
| MANLY | | | | | | | | | |
| | | | | | | | | | |
| | | All costs include GST | | | | | | | |
| Item | | RBS | | FBS | CBC | | | | |
| Fixed contractor Costs excluding door supply cost | \$ | 1,639,520.00 | \$ | 1,590,984.00 | \$ | 2,032,964.00 | | | |
| Provisional sum items (concrete spalling and coating | | | | | | | | | |
| stripping) | \$ | 135,000.00 | \$ | 121,055.00 | \$ | 126,731.68 | | | |
| Subtotal | \$ | 1,774,520.00 | \$ | 1,712,039.00 | \$ | 2,159,695.68 | | | |
| Contingency | \$ | 120,000.00 | \$ | 120,000.00 | \$ | 120,001.00 | | | |
| HBCF Insurance | \$ | 88,726.00 | \$ | 85,601.95 | \$ | 107,984.78 | | | |
| Superintendent/ Consultancy/ project Management fees | \$ | 159,706.80 | \$ | 154,083.51 | \$ | 194,372.61 | | | |
| Total Recommended Funding | \$ | 2,142,952.80 | \$ | 2,071,724.46 | \$ | 2,582,054.08 | | | |